

FIG. 1

## SECURITY CAMERA INTERFACE

Daryn Kiely, Tim Moser, Derrick Price Prepared by Justin White of Beyer Weaver & Thomas, LLP, (650) 961-8300, Ref: IGT1P097

2/5






FIG. 2

## SECURITY CAMERA INTERFACE

Daryn Kiely, Tim Moser, Derrick Price



4/5



## SECURITY CAMERA INTERFACE Daryn Kiely, Tim Moser, Derrick Price

Prepared by Justin White of Beyer Weaver & Thomas, LLP, (650) 961-8300, Ref: IGT1P097 5/5




FIG. 5

	Security Realtime Event Display					烂
	Ellers Seventy Display Help	100	en an artista	Company of		707
1	X Date/Time	Asset Num	bei Machine Loca	ion Even Num	ber Event Description	1760
•	<b>⊘</b> Wed Feb 03 09:37:14 1999	90000	DP3X01	6901	Card Inserted	
	<b>(1)</b> Wed Feb 03 09:37:14 1999	90000	DP3X01	0318	Memory Error Reset	
,	👢 Wed Feb 03 09:37:14 1999	9000D	DP3XD1	0205	illegal Drop Door Open	
	₩Wed Feb 03 69:37:14 1999	90000	DP3XD1	0105	. DBill Acceptor Jam	
	Wed Feb 03 09:37:14 1999	90000	DP3X01	1005	Start Meter_Event Test	
	Wed Feb 03 09:37:14 1999	90000	DP3XD1	<b>0</b> 205	Illegal Drop Door Open	
	<b>⊘</b> Wed Feb 03 09:37:14 1999	90000	DP3XD1	5901	Card Inserted	
_	Wed Eeb 03 09:37:14 1999	90000	DP3XD1	0316	Memory Error Reset	
2 –	🔀 Wed Feb 03 09:37:14 1999 -	90000	DP3X01	0205	Megal Drop Door Open	
	₩Wed Feb D3 69:37.14 1999	90000	DP3X01	0106	DBill Acceptor Jam	
	Wed Feb 03 09:37:14 1999	90000	DP3XD1	1005	Start Meter_Event Test	
	🙎 Wed Feb 03 09:37:14 1999	90000	DP3X01	0205	lllegal Drop Door Open	
	<b>∛O</b> Wed Feb 03 09:37:14 1999 -	90000	DP3X01	0901	Card Inserted	
	Wed Feb 03 09:37:14 1999	90000	DP3X01	0318	Memory Error Reset	
	Wed Feb 03 09:37:14 1999	900DD	DP3X01	<b>0</b> 205	illegal Drop Door Open	
	<b>₩</b> Wed Feb 03 09:37:14 1999 -	95000	DP3X01	9105	DBill Acceptor Jam	
	Wed Feb 03 09:37:14 1999	90000	DP3X01	1005	Start Meter_Event Test	
	<b>S</b> Wed Feb 03 09:37:14 1999	9 <b>0</b> 000	DP3X01	0205	lliegal Drop Door Open	
	Wed Feb 03 69:37:14 1999	90000	DP3XD1	<b>0</b> 901	Card Inserted	
	Wed Feb 03 09:37:14 1999	90000	DP3X01	0318	Memory Error Reset	
	Wed Feb 03 09:37:14 1999	9D000	DP3X01	0205	Illegal Drop Door Open	
	₩Wed Feb 03 09:37:14 1999	95000	DP3X01	0108	DBill Acceptor Jam	
	Wed Feb 03 09:37:14 1999	90000	DP3X01	1005	Start Meter_Event Test	
	🕵 Wed Feb 03 09:37:14 1999	90000	DP3X01	0205	illegal Drop Door Open	
	Wed Feb 03 09:37:14 1999	90000	DP3X01	0301	Card Inserted	

603

600 <

FIG. 6